


FOTNF Maintenance Work At Sears-Kay Ruin 2021

Before and After




Post-Fire erosion Control Along the Trail





Compound 5





Compound 4



Compound 4




(same room, from opposite direction)

Compound 4



(same room, from different direction)






Compound 3




Compound 3



Compound 3




Looking up at the Top








Trail Work




After Shots from
Compound 1







And a last look down the ridge



Sears-Kay Ruin Adopt-a-Site Spring 2021

